


Cluster

H-leg Conference Table (Two-section)

NOVAH[®]



NOVAH System Technology Co.,Ltd.
Tel: 400-115-1688
Web: www.novah.cc
Mail: int@novah.cc

NOVAH[®]

Product Parts List



Cross countersunk self-tapping
screw 4*16



Cross countersunk self-tapping
screw 4*45



Cross big flat head
self-tapping screws 5*20



Hexagon socket cylindrical
head screw M6*16



Hexagon socket cylindrical
head screw M6*50



Hexagon socket cylindrical
head screw M10*60,
including spring washer
+ flat washer



Hexagon socket cylindrical
head screw M8*30



Tapered support of
table board



Upper conical connector
of beam




Lower conical connector
of beam



Connecting sheet of
table board


Step 1

- 1.Cluster H-leg conference table, beam bracket A and bracket B
- I.Paste single-sided magic tape on the bottom surface at the joint of beam;
- II.While connecting the beam bracket, the joint protrudes by about 5mm;Tighten them with screws and adjust to achieve alignment




Step 2

- 1.Install the H-leg, beam bracket and thread the power cord
- I.The leg and beam bracket are connected firmly with screws, upper and lower conical connector;
- II.The steel frame is placed properly. Remove the trim of leg column and thread the power cord



Step 3

1. Install the middle support of beam, middle support of upper beam of leg and steel socket panel




Step 4

1. Install the table leg stand and table board

I. Firstly, correctly assemble the table boards with four connecting sheets of table board;

II. Secondly, connect the steel kickstand and table board with screws



Step 5


1.Complete the power track and adapter

I.First, open the slender strip cover in the middle of power track;

II.Then, connect the power track and table board with screws

III.Install the slender strip cover after fixing the power track;

IV.Install the adapter



Step 6

1.The installation is complete

