
Cluster

Single-sided Rectangular 3-seat Workstation (A)









Web: www.novah.cc Mail: int@novah.cc



Product Parts List





Cross recessed countersunk head tapping screw (4*20) Cross recessed countersunk head tapping screw (4*45) Cross recessed milling-end screw (M4*10)







Hexagon socket cylindrical head screw (M6*16) Hexagon socket cylindrical head screw (M6*50) Tapered support of table board (NFCA-2002)







Conical upper connector of beam (NFCA-2003) Conical lower connector of beam (NFCA-2004)



Screen routing sheet

(NF4B-3003)






Flat washer (PD06AT3) Middle legs' upper beam end member (NFCE-1107)

Beam support (NFCE-1108)


Step 1

1.Install door-like side foot




Step 2

1.Install the middle leg (routing type)




Step 3

1.Install the table leg stand



Step 4

1.Install the countertop



Step 5

M6*16 x6

1.Install the desktop screen and wire box

Flat washer x6 Flat washer x6 Cross recessed countersunk head tapping screw 5*20 x4*3=12 Hexagon socket cylindrical head machine screw

Step 6

1.The installation is complete

