
Cluster

Double-sided Rectangular 4-seat Workstation (B)









Tel: 400-115-1688 Web: www.novah.cc Mail: int@novah.cc



Product Parts List



Cross recessed countersunk

head tapping screw

(4*20)

())

Cross recessed countersunk head tapping screw (4*45)



Cross recessed milling-end screw (M4*10)



Hexagon socket cylindrical head screw (M6*16)

Hexagon socket cylindrical head screw (M6*50)

Hexagon socket cylindrical head screw (Including spring washer) (M10*65)



Screen routing sheet

(NF4B-3003)

Conical upper connector of beam

Tapered support of table board (NFCA-2002)



(NFCA-2003)

Conical lower connector of beam (NFCA-2004)



Flat washer (PD06AT3)



Middle leg support (NFCE-1106)



Middle legs' upper beam end member (NFCE-1107)



Beam support (NFCE-1108)


Step 1

1.Install door-like side foot

Tapered support of table board NFCA-2002 x4

Step 2

1.Install the middle leg (routing type)




Step 3

1.Install the table leg stand

Note: Optional; If not equipped, screws of beam support are 4*20 € Middle support of beam NPCA-2100 x4 Beam support NFCE-1108 x8 Beam's conical upper Enlargement view of beam and lower connector and leg connection NPCA-2003/2004 x8

Step 4


1.Install the countertop



Note: The table plate is screwed in place after aligning with the table screen inserts and the table frame!


Step 5

1.Install the desktop screen and wire box



Step 6

1.The installation is complete



Make sure to fasten the screws of flat guard board to avoid excessive gap and abnormal noise!