
Cluster

Conference Desk(3-section)









Web: www.novah.cc Mail: int@novah.cc



Product Parts List



Cross recessed countersunk

head tapping screw

(4*20)

())

Cross recessed countersunk head tapping screw (4*45)



Cross recessed milling-end screw (M4*10)





Hexagon socket cylindrical head screw (M6*16)

Hexagon socket cylindrical head screw (M6*50)

Hexagon socket cylindrical head screw (Including spring washer) (M10*65)



Tapered support of table board

(NFCA-2002)



Screen routing sheet (NF4B-3003)



Conical upper connector of beam (NFCA-2003)



٥



Flat washer (PD06AT3)

Middle leg support (NFCE-1106)



Conical lower

connector of beam

(NFCA-2004)

Middle legs' upper beam end member (NFCE-1107)



Beam support (NFCE-1108)


Step 1

1.Install door-like side foot

Tapered support of table board NFCA-2002 x4

Step 2

1.Install the middle leg (routing type)




Step 3

1.Install the table leg stand

Note: Optional; If not equipped, screws of beam support are 4*20 Middle support of beam NPCA-2100 x6 Beam support NFCE-1108 x12 Beam's conical upper and lower connector NPCA-2003/2004 x12


Step 4

1.Install the countertop



Step 5

1.Install the wire box



Step 6

1.The installation is complete

