





Product Parts List





(Hexagon socket cylindrical head screw M6-12)


(Cross recessed pan head tapping screw ST5.0-20)

Step 1

1.Place the bracket arm of the hanging screen panel in the direction indicated here

2.Install the bracket arm for the hanging screen panel

(Hexagon socket pan head screw M6-12)




Step 2

1.Place the hanging screen panel under the desktop, snug against the edge of the desktop

2.Install the hanging screen panel

(Cross recessed pan head tapping screw ST5.0-20)



Step 3

1.The installation is complete

