
LOOP Hanging Screen Panel









Web: www.novah.cc Mail: int@novah.cc



Product Parts List



13x(Cross recessed flat head self-tapping screw)



6x(Hex socket countersunk head screw)




3x(Hex Socket Set Screw_Stainless Steel) (M6*16)

Step 1

1.Install the screw lever

Step 2



If the angle of the L-shaped iron piece is less than 90°, slightly loosen the hex socket countersunk screw, then use the set screw (2) to adjust the screen to a vertical angle. Note: In principle, the angle should not exceed 90°. If it does, add a spacer at the connection point (3).

Step 3

1.Mount to desktop

