


Cluster

120° Workstation

NOVAH



NOVAH System Technology Co.,Ltd.
Tel: 400-115-1688
Web: www.novah.cc
Mail: int@novah.cc

NOVAH

Product Parts List



Cross recessed countersunk
head tapping screw
(4*20)



Cross recessed countersunk
head tapping screw
(4*45)



Cross recessed
milling-end screw
(M4*10)



Hexagon socket cylindrical
head screw
(M6*16)



Hexagon socket cylindrical
head screw
(M6*50)



Hexagon socket cylindrical
head screw
(Including spring washer)
(M10*65)



Tapered support of
table board
(NFCA-2002)



Conical upper connector
of beam
(NFCA-2003)



Conical lower
connector of beam
(NFCA-2004)



Flat washer
(PD06AT3)



Middle leg support
(NFCE-1106)



Middle legs' upper beam
end member
(NFCE-1107)



Beam support
(NFCE-1108)




Intermediate Foot
Line Straightener
(NFCE-1210)



Cluster center leg fastener
(NFCE-1209)


Step 1

1. Install door-like side foot



Step 2


1. Install the middle leg (routing type)



Note: Center legs are used for 120° workstations seating six or more.


Step 3

1. Install the table leg stand




Step 4

1. Install the countertop and junction box




Step 5

1. Install the desktop screen




Step 6

1. The installation is complete



Cluster 120° 3-seat



Cluster 120° 6-seat